

DECOTEX GLOW IN THE DARK PRINTABLE APPLICATION INSTRUCTIONS:

- 1 Heating Temperature: **150 - 160** degree Celcius
- 2 Pressure & Time: **10-12** seconds with Medium pressure.
- 3 Washing Temperature: under 40 degree Celcius
- 4 Application Instruction:
 - Heating and Cutting Instruction:
 - Print you graphic on PU film layer with solvent based ink printer and cut alongside what is printe
 - Remove unwanted area, remove top pet protective liner using application tape or paper
 - Heat Press Application
 - Press at the above heating temperature for around 8-10 seconds from top pet protective film with Medium pressure
 - Lift up press.
 - Warm peel
- 5 Care Guide
 - Turn garment inside out, machine wash.
 - Cool/warm water temperature, line dry
- 6 Washing Test Results: After 5 cycles (30 minutes per cycle and natural line-dry clothes before another another cycle.) Under 40 degrees Celcius; no excessive change in adhesion, appearance, and color

DECOTEX PRINTABLE SUBLIBLOCK APPLICATION INSTRUCTIONS:

- 1 Heating Temperature: **150 - 160** degree Celcius
- 2 Pressure & Time: **8-10** seconds with Medium pressure
- 3 Washing Temperature: under 40 degree Celcius
- 4 Application Instruction:
 - Heating and Cutting Instruction:
 - Print you graphic on PU film layer with solvent based ink printer and cut alongside what is prinec
 - Remove unwanted area, remove top pet protective liner using application tape or paper
 - Heat Press Application
 - Press at the above heating temperature for 8-10 seconds from top pet protective film with Medium pressure
 - Lift up press
 - Warm peel
- 5 Care Guide
 - Turn garment inside out, machine wash.
 - Cool/warm water temperature, line dry
- 6 Washing Test Results: After 10 cycles (30 minutes per cycle and natural line-dry clothes before another cycle.) Under 40 degrees Celcius; no excessive change in adhesion, appearance, and color